## HHSEGS (11-AFC-02) TESTIMONY OF C.R. MACDONALD

## FACILITY DESIGN EXHIBIT 717

**PHOTO GALLERY** 

Facility Design: Photo 1
Saturated soil causes van in storage at Charleston View to sink. 4/25/12.



Facility Design: Photo 2
Saturated soil causes van in storage at Charleston View to sink. 4/25/12.



 $\textbf{Facility Design: Photo 3}\\ \textbf{Saturated soil cause sinking of equipment during July 2012 flood event at Genesis Solar site.}$ Photo Source: CEC



Facility Design: Photo 4
Saturated soil cause sinking of equipment during July 2012 flood event at Genesis Solar site.
Photo Source: CEC



Facility Design: Photo 5
Saturated soil cause sinking of equipment during July 2012 flood event at Genesis Solar site.
Photo Source: CEC



Facility Design: Photo 6
Saturated soil cause sinking of equipment during July 2012 flood event at Genesis Solar site.
Photo Source: CEC

